



These faces are generally grass & light bush covered. Due to steep slope there is surface hill creep

Thinly bedded blue grey muddy siltstone with iron staining on joints.

Probable extent of embankment fill

Approximate limit of previous slope

Slightly higher area

Bush covered slope

Stream 'B'

Fault 'B'

Issue with report.		20/1/84	
Rev	Reason for Revision/Issue	Drawn	Ch'kd

**kirta**  
 Kingston Reynolds Thom and Allardice Limited  
 Engineers Architects Planners Quantity Surveyors  
 PO Box 4498 Auckland New Zealand Ph 795 700

MAKORORI BEACH TOWNSHIP  
 COOK COUNTY  
 ENGINEERING GEOLOGY MAP LOT 14 TO LOT 43.

SCALES: 1:1000	
PROJECT	DRAWING
2535	FIG. 6
DATE DEC '83	DRAWN K.R. [Signature] CHK'D [Signature]